

Customer Service Report

Customer Purchase Order Number 51001950				
1-2091256793	1-YNFPFH		03-Jun-2009	
Service Start Date		Service	End Date	
10-Jun-2009 09:00		10-Jun-	2009 10:30	

Equipment Location:

Attention: Jim Hanchett Commonwealth of Massachusetts Western Mass Public Health 181 Stockbridge Rd Morrill Bldg AMHERST MA 01003 United States

Telephone: (413) 545-2607

Please Direct Inquiries To:

Telephone: (800) 979 4811 or +1 (408) 345 8511 Email: service.automation@agilent.com

	Product Number/ Description	Manufacturer	Serial Number
	G1098A 5973 MSD diffusion-pump mainframe	Agilent Technologies	US82311418
		Inc	
ı			

Problem Description:

room N251 US82311418 Needs EM horn replaced

Services Provided:

Replaced Multiplier Horn pumped system down and performed autotune.

Parts Used		Manufacturer	Quantity
05971-80103 Electron multiplier replacement horn		Agilent	1 EA
		Technologies Inc	
	Time		
Standard Hours	1.5		
Travel Hours	3.5		
Overtime Hours	0.0		
Customer Engineer Name		Customer Engineer Signature	Date
Customer Name		Customer Signature	Date
		This is not an invoice	
Customer Comments:			
Customer Comments:		This is not an invoice	